

WASHER BASED WING NUTS Zinc Die Cast Alloy

- Standard materials: zinc

| Thread Size | Wing Spread | Total Height | Washer Outside Diameter | Individual Wing Width | Between Wings | Washer Thickness | Wing Thickness At Base | Boss & Washer Height |
|-------------|-------------|--------------|-------------------------|-----------------------|---------------|------------------|------------------------|----------------------|
| 8-32 | 7/8 | 7/16 | 5/8 | 0.207 | 0.250 | 0.032 | 0.125 | 0.182 |
| 10/24 | 7/8 | 7/16 | 5/8 | 0.207 | 0.250 | 0.032 | 0.125 | 0.182 |
| 10-32 | 7/8 | 7/16 | 5/8 | 0.207 | 0.250 | 0.032 | 0.125 | 0.182 |
| 1/4-20 | 1 | 1/2 | 3/4 | 0.234 | 0.312 | 0.035 | 0.140 | 0.205 |
| 1/4-20 | 1-1/8 | 37/64 | 7/8 | 0.260 | 0.375 | 0.040 | 0.150 | 0.225 |
| 5/16-18 | 1-1/8 | 37/64 | 7/8 | 0.260 | 0.375 | 0.040 | 0.150 | 0.225 |
| 3/8-16 | 1-1/8 | 37/64 | 7/8 | 0.260 | 0.375 | 0.040 | 0.150 | 0.225 |

Michigan

400 N. Clinton St.
Stockbridge, MI 49285
Phone: 517-851-8757
Fax: 517-851-7722

Tennessee

3100 Ambrose Ave.
Nashville, TN 37207
Phone: 615-352-6701
Fax: 615-352-6722

Wisconsin

Milwaukee, WI 53220
Phone: 414-344-8034